

All orders are governed by the GES Payment Policy and GES Terms & Conditions of Contract as specified in this Exhibitor Services Manual.

## Architectural Digest Home Design Show

New York City Passenger Ship Terminal  
March 22 - 25, 2012

### Hanging Signs

**GES is responsible for assembly, installation, and removal of all hanging signs.**

**Remember:**

1. All signs must be designed to comply with Show Organizer rules and regulations and facility limitations.
2. Make sure all signs, with the exception of cloth banners and signs under 100 lbs., have structurally engineered rigging points as well as blueprints displaying a current structural engineer's stamp.
3. If your sign requires electricity, make sure it is in working order and in accordance with the National Electric Code. Place your order for electrical services and electrical labor on the Electrical Service Order Form.
4. Include Exhibitor contact information with the order.
5. **Include engineer-stamped assembly and hanging instructions with the order. GES accepts no liability for any work completed without such instructions, when required. Work is done at Exhibitor's risk and Exhibitor shall indemnify and defend GES and Show Organizer from any claims arising out of or related to the installation or dismantle of any sign without approved drawings.**

### Truss & Hoists

**GES is responsible for assembly, installation, and removal of all truss.**

**Remember:**

1. All truss must be designed to comply with Show Organizer rules and regulations and facility limitations.
2. All truss must be from a recognized manufacturer. Manufacturer load specifications for your truss must be at show site prior to rigging.
3. **Climbing on truss is strictly prohibited.**
4. All lamps and fixtures to be attached to truss must be in good working order and in compliance with the National Electric Code. Place your order for electrical services and electrical labor on the Electrical Service Order Form.
5. All hoists must be from a recognized manufacturer and must be in good working order.
6. Hoist maintenance records should be available for inspection by GES.

**Please complete and return the  
Hanging Sign / Truss Labor Order Form (H-2) by February 28, 2012.**

By sending us this information in advance you will help us assure your sign is properly assembled and installed.

### Shipping Instructions

**All hanging signs should be received in advance at the GES Warehouse by March 15, 2012.**

Please ship all hanging signs in a separate container with the special sign label provided after this form on H-1a. Mark bill of lading "Hanging Sign". Prepay all shipments. Collect shipments will not be accepted.

#### Need Assistance?

Toll Free: 800.475.2098 | Tel: 702.515.5970 | [www.ges.com/chat](http://www.ges.com/chat)

